MS-DOS Installation Instructions

Introduction

MS-DOS comes pre-installed on the PowerStation. If for some reason you need to reinstall MS-DOS, you can do so using the MS-DOS 6.22 and Utilities Installation disk (KA-72953) that was shipped with your PowerStation. This disk automatically installs the MS-DOS system files and utilities to a formatted flash drive or hard drive.

This document provides instructions for installing or reinstalling MS-DOS to a CTC PowerStation with a hard drive or a Compact Flash card.

Hard Drive Instructions

The Hard Drive instructions describe how to install MS-DOS system files and utilities to a hard drive. Follow these steps if your PowerStation supports a hard drive.

To install MS-DOS to the hard drive, complete the following steps:

- 1. Insert the MS-DOS 6.22 and Utilities Installation disk (KA-72953) into the floppy drive of your PowerStation.
- 2. At the DOS prompt, type a: and then press **Enter**. You will now be at the root directory of drive A.
- 3. Type install a: c: and then press Enter.

The following message appears:

You are about to install MS-DOS 6.22 on destination drive C.

4. Press Y if the destination drive is correct.

The install program will copy the MS-DOS system files to your hard drive.

When the install program is finished copying the system files, the following message appears:

Do you want to install all the MS-DOS utilities? Select Y to do a typical installation of the most-used MS-DOS utilities, which uses about 800 Kbytes of disk space. Select N to do a minimal install of only a few MS-DOS utilities.

CTC Parker Automation A3-05927-100

Do you want to install all the MS-DOS utilities?

5. Press **Y** to install all the MS-DOS utilities or **N** to install a few MS-DOS utilities.

Note You will need about 800 Kbytes of disk space on your hard drive to install all the MS-DOS utilities.

The install program will copy the MS-DOS utilities to a DOS directory on the hard drive. When the installation is complete the following message appears.

MS-DOS Installation complete.

Compact Flash Instructions

The Compact Flash instructions describe how to install MS-DOS system files and utilities to a formatted Compact Flash card. Follow these steps if your PowerStation supports a Compact Flash card.

To install MS-DOS to the Compact Flash, complete the following steps:

1. Turn off the PowerStation.

Important Make sure the PowerStation is turned off when inserting or removing the Compact Flash card.

- 2. Remove the flash card from the PowerStation's flash card slot.
- 3. Insert the Compact Flash card into a Type II PCMCIA slot on your PC, using the Compact Flash-to-PCMCIA adapter.

The PCMCIA drivers should recognize and configure the card as an ATA card, assigning an additional drive letter for the card (e.g., D:).

Note In this example, drive D represents the PCMCIA card; however, your system may assign a different drive letter to the PCMCIA card.

- 4. Insert the MS-DOS 6.22 and Utilities Installation disk (KA-72953) into the floppy drive of your PC.
- 5. Restart your PC so that you boot from drive A.

2 CTC Parker Automation

- 6. At the DOS prompt, type install a: d:
- 7. Press Enter.

The following message appears:

You are about to install MS-DOS 6.22 on destination drive D.

8. Press **Y** if the destination drive is correct.

The install program will copy the MS-DOS system files to the destination drive. When the install program is finished copying the system files, the following message appears:

Do you want to install all the MS-DOS utilities? Select Y to do a typical installation of the most-used MS-DOS utilities, which uses about 800 Kbytes of disk space. Select N to do a minimal install of only a few MS-DOS utilities.

Do you want to install all the MS-DOS utilities?

9. Press **N** to install only a few MS-DOS utilities.

Important We recommend that you perform a minimal install for Compact Flash systems. Typically there is not enough disk space on the Compact Flash to install all the MS-DOS utilities.

The install program will copy the MS-DOS utilities to a DOS directory on the Compact Flash. When the installation is complete, the following message appears:

MS-DOS Installation complete.

- 10. Eject the Compact Flash-to-PCMCIA adapter, and remove the Compact Flash from the adapter.
- 11. Insert the Compact Flash card into the PowerStation's flash card slot.
- 12. Power up the PowerStation.

CTC Parker Automation 3